



----- Indicative location of existing cornice to ceiling


























Drawings to be read in conjunction with: Slattery Historic Building Consultant Report on the 'Architectural / Historic Significance of DunLeary House, DunLeary Hill and Cumberland Street Dun Laoghaire Co Dublin (A Proposed Protected Structure) & Observations on the Potential Impact of the Proposed Works. November 2021